



SUNMAX 2000 PORTABLE DATA TERMINAL Set Up Parameters

Your Sunmax 2000 Portable Data Terminal should be set up for standard PC and commonly used bar code symbologies. If it is necessary to change your parameters, the following instructions will help you navigate your system ...

When the unit is powered on, the screen will show

```
<MAIN MENU>
1 - COLLECT          2 - PROGRAM
3 - DOWNLOAD         4 - UPLOAD
5 - NON-PORTABLE    6 - SET UP
```

Press – 6 (Set Up)

```
<SET UP MENU>
ENTER SELECTION:

HIT SP FOR OPTIONS
```

The SP (space) button will show the set up options you might want to change. Following are the most common library selections, and their parameters. (For example, if you press “A” to check the setting for Code 39 – it should read ACFIJ).

A – C39 (Code 39)	- ACFIJ
F – CBR (Codabar)	- CE
L – Interface	- A (standard PC or PC compatible)
M – Scan Key	- ACEH
V – Date & Time	-use MO/DA/YR 00:00

(shift) 2 – Clear Data Memory – ALL THE DATA WILL BE DELETED. ARE YOU SURE? (Y/N) – press the red “enter(yes)” key

The Sunmax 2000 is capable of a wide range of options – please call if you would like further details or guidance through the set up procedure:

Edmonton, Alberta area: 780 459 3577
Toll Free (North America): 877 459 3577